



INTERNATIONAL TESTING CENTRE

TEST CERTIFICATE

Customer Name: Yaqoob Tanners.

Test report No.: 2K2401275

Contact person

: Mr.

Date of Entry : 19.01.2024

Address

: 67/8, Pokharpur, K.D.A. Colony, Jajmau, Kanpur (U.P.) - 208010 Sample description: Safety Shoe (Size – 8), Colour: Black

Details

: Article -ZM-7L,

Page : 1/1

Specification

: IS - 15298 (P-2): 2016, Classification - I

Testing period

: 22.01.2024 to 30.01.2024

Reporting date: 01.02.2024

Laboratory Environment

Temperature

27 +/-2°C

Relative Humidity

65+/-5% The sample was conditioned for 48 hours

S.N	o. Test Name	Clause	Value	Requirement	Conformity
1.Tes	et on Whole Footwear (5.3)			•	J
a.	Upper/Outsole bond	5.3.1.2	4.7 N/mm	4 N/mm (minimum)	Conforms
b.	Impact resistance – 200 J	5.3.2.3	17.0 mm No crack was observed.	14.0 mm (min.), toecap shall not develop any cracks on the test axis.	Conforms
Э.	Compression resistance- 15 kN	5.3.2.4	18.0 mm	14.0 mm (min.)	Conforms
d.	Slip resistance – 5.3.5 (SRA)	5.3.5.2	0.30 0.38	Coefficient of friction for Condition A(Forward heel slip)≥0.28 Condition B(Forward flat slip)≥ 0.32	Conforms
е.	Antistatic Test	6.2.2.2	Dry: 873 M Ohm Wet: 305 M Ohm	100 k Ohm – 1000 M Ohm	Conforms
2.Tes	t on Upper (5.4)		Latin September 1901		
ì.	Tear strength	5.4.3	218 N	120 N (minimum)	Conforms
٥.	Tensile strength	5.4.4	22.4 N/mm ²	15 N/mm ² (minimum)	Conforms
3.Tes	t on Sole – 5.8			The state of the s	
ì.	Abrasion resistance	5.8.3	237 mm ³	250 mm ³ (max.) density ≤ 0.9 g/cm ³	Conforms

Brand:- Zain

Rajesh Mishra (Senior Technologist) **Authorized signatory**

Shailendra Saxena (Head -Physical Laboratory) Authorized signatory

*** END OF TEST REPORT ***

1. This report is for technical information of the client only. Not for advertisement, promotion, publicity litigation or legal purpose.

2. This institute shall be indemnified against any dispute arising out of issue of this report.

3. Sample not drawn by FDDI and the test results relate only to the material tested.

4. The report must not be reproduced except in full without approved of FDDI.